جامعة السلطان قابوس
Sultan Qaboos University

Requisition Form

Requisition Number: 1234/26/0111

Last Date for Submission: 14/09/2026

S.N.	SQU Product Code	Description	Qty	UOM	Remarks
1	SPRSEIPTS0399	REPAIR, ADJUSTMENT AND CALIBRATION	1	Nos	Repair of the equipment: Electrically operated bed. Manufacturer: ISIK Model : HKE-LXSO Fault description: Control Buttons are giving wrong functions. Those suppliers with the means to repair this equipment must visit the site and inspect the fault then submit their offer accordingly. For site vist coordination please contact: *Eng. Rashid 24142798 - rashid1@squ.edu.om. *Mrs. Samia 24145446 - samiar@squ.edu.om